

Model: BOSTON STONE 59,6X180(A) Codes: 100179318 Water absorption: Bla - Porcelanico (E<=0.1%)



Sistema DAPc[®] Declaración Ambiental de Productos de Construcción

| DIMENSIONAL FEATURES UNE-EN ISO 10545-2 | | | |
|--|-------------|----------|--|
| Thickness | 11.5 MM | +/-5%* | |
| Width | 596 MM | | |
| Length | 1800 MM | | |
| Length and width deviation | Below 0.15% | +/-0.3%* | |
| Side straightness deviation | Below 0.15% | +/-0.3%* | |
| Squareness deviation | Below 0.15% | +/-0.3%* | |
| Surface flatness deviation | Below 0.15% | +/-0.4%* | |
| *ISO-13006:2018 UNF-EN 14411:2016 | | | |

| MECHANICAL FEATURES UNE-EN ISO 10545-4-6-7-11 | | | |
|--|------------------|------------|--|
| Breaking strength | 4047.9 N | >1300N* | |
| Modulus of rupture | 51 N/MM2 | >=35N/mm2* | |
| Abrasion resistance | PEI 3 / 600v | | |
| Crazing resistance | Resists 3 cycles | | |
| *ISO-13006:2018 UNE-EN 14411:2016 | | | |

| HYGIENIC FEATURES UNE-EN ISO 10545-13-14:1995 | | |
|--|--|---------|
| Chemical resistance | Class "A" for swimming pools and cleaning products (resists attack). Minimum Class "B" for acids and bases | B Min.* |
| Stain resistance | Class 5. Easy cleaning with water | 3 Min.* |
| *ISO-13006:2018 UNE-EN 14411:2016 | | |

| Technical code-1 Use on heavy traffic floors ANTI-SLIP VALUE EN 16165: 2022 / ASTM C1028 Dynamic coefficient of friction >0,42 Slip resistance (pendulum-wet) CL1 | | SCOPE OF USE | |
|--|---------------------------------|-----------------------------|--|
| EN 16165: 2022 / ASTM C1028 Dynamic coefficient of friction >0,42 | Technical code-1 | Use on heavy traffic floors | |
| | | | |
| Slip resistance (pendulum-wet) CL1 | Dynamic coefficient of friction | >0,42 | |
| | Slip resistance (pendulum-wet) | CL1 | |
| 4s WET-27/DRY-52 | 4s | WET-27/DRY-52 | |

*ISO-13006:2018 UNE-EN 14411:2016



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.

100179318 BOSTON STONE



| | PACKING | |
|------------------------|-------------------|--|
| Sales units per box | 2.145693 M2/BOX | |
| Sales units per pallet | 51.496621 M2/PAL | |
| Sales units per unit | 1.072846 M2/PIECE | |



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.