







DIMENSIONAL FEATURES UNE-EN ISO 10545-2					
Length	1200 MM				
Thickness	6 MM				
Width	1200 MM				
Length and width deviation	Below 0.15%		+/-0.3%*		
Side straightness deviation	Below 0.15%		+/-0.3%*		
Squareness deviation	Below 0.15%		+/-0.3%*		
Surface flatness deviation	Below 0.15%		+/-0.4%*		
*ISO-13006:2015 UNF-EN 14411:2017					

MECHANICAL FEATURES UNE-EN ISO 10545-4-6-7-11				
Breaking strenght	>1100 N			
Modulus of rupture	>45 N/MM2			
Abrasion resistance	<140			
*ISO-13006:2015 UNE-EN 14411:2017				

	HYGIENIC FEATURES UNE-EN ISO 10545-13-14
Chemical resistance	CLASE A
Stain resistance	5
Resistance to cold food products	АРТО
Resistance to hot food products	АРТО
Fastness to rubbing	АРТО
Dimensional stability at elevated temperature	CUMPLE
Climate shock test. resistance index	RESISTE
Resistance to thermal shock	RESISTE
Flammability	A1
*ICO 12006-2016 LINE EN 14411-2017	

*ISO-13006:2015 UNE-EN 14411:2017



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.

PORCELANOSA Grupo

100288110 VIOLA BLUE SILK

	ANTI-SLIP VALUE CEN/TS 41901/02, DIN-51130 y ASTM A137.1
Slip resistance (pendulum-wet)	CLO
Resistance to bacteria	АРТО
Resistance to cleaning products	АРТО
Resistance to bathroom cleaning products	АРТО
Resistance to cigarette burns	АРТО
4s	DRY>36-LOW_WET<25-HIGH
Slip resistance (pendulum-dry)	>45
*ISO-13006:2015 UNE-EN 14411:2017	
	SCOPE OF USE
Technical code-1	Use on light traffic floors
Technical code-2	Dry interior floors
	PACKING

Sales units per box	2.88 M2/BOX	
Sales units per pallet	74.88 M2/PAL	
Sales units per unit	1.44 M2/PIECE	



45

SGS

Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.